

TECHNICAL & SAFETY COMMITTEE

INTERNATIONAL PARACHUTING COMMISSION




Technical & Safety Information Notice No.	BARTACKING OF RSL/SKY HOOK LANYARD W.N. 51
Date of Issue	20 September 2015
Subject Matter and Applicability	<p>PRODUCT SERVICE BULLETIN 2015-01 (PSB # 2015-01) issued 16 September 2015 by Parachute Systems, 32 Melbourne Road, Dalbridge, Durban, South Africa 4014</p> <p>ISSUE IDENTIFICATION: PSB # 2015-01</p> <p>BARTACKING OF RSL/SKY HOOK LANYARD NAME: RSL/Sky hook lanyard (Part Nr. PSP-0303) Fitted to Parachute Systems Vortex Harness containers. Affected Vortex Rigs: All rigs fitted with a new style RSL and Sky hook system on the right side of the rig. As from 07/2014</p> <p>Serial Numbers: Sky-hook systems 0323182,0323198,0323210,0323213,0323220,0323221,0323226, 0323233,0323236,0323241,0323244,0323247,0323249,0323250,0323253, 0323254,0323256,0323259,0323266,0323269,0323271,0323273,0323274, 0323276,0323285,0323288,0323291,0323300,0323305,0323308,0323339, 0323416,0323418,0323419,0323422,0323425,0323427,0323430,0323431, 0323433,0323436,0323437,0323440,0323443,0323446,0323447,0323450, 0323456,0323457,0323458,0323459,0323468,0323471,0323473,0323475, 0323476,0323477,0323478,0323479,0323480,0323481,0323488,0323490, 0323494,0323497,0323498,0323501,0323502,0323507,0323508,0323509, 0323510,0323511, 0323513,0323515,0323516,0323518,0323580,0323583</p> <p>Serial Numbers: RSL Systems 0323489,0323491,0323495,0323503,0323504,0323512,0323527, 0323589</p>
Details	<p>SKY HOOK LANYARD CONSTRUCTION AND INSPECTION PROCEDURE: The Sky-hook lanyard, which is manufactured by PS has been found, in some cases, to have a construction omission. The yellow loop is not included in the bar tacks on the lanyard in some cases. This could tear off when the RSI/Skyhook is activated. Because the Velcro is fitted over the bar tacks on one side of the lanyard, it is not possible to see if they are through the yellow loop</p>

when inspecting a completed lanyard.
While there have been no reports on the lanyard pulling apart, we advise that the affected rigs be bar tacked or zigzagged IMMEDIATELY BEFORE THE NEXT JUMP.
We apologise for the inconvenience and strongly urge that all of these items are inspected before the next jump even if serial numbers are not on the above list.

PROCEDURE TO FOLLOW:

To be carried out by a Master Rigger or equivalent

1. Add two Bar tacks or two rows of Zigzag stitching over the existing bar tacks. These will then be visible on both sides of the lanyard, through the Velcro tape.
2. This can be done without the reserve being opened.



Compliance	COMPLIANCE DATE: 16 September 2015 STATUS: MANDATORY BEFORE NEXT JUMP
Concerned Publication	Distribution by Parachute Systems 1. All Parachute Systems Dealers 2. DZ's 3. Parachute Association of Southern Africa 4. All Parachute Rigging Forums Distribution by IPC Technical & Safety Committee E-mail to all T&S Officers; FAI/IPC website
Authority	Christopher Dales, CEO Parachute Systems. CC 32 Melbourne Road Durban, South Africa 4014 Tel: (031) 304 8035 / Fax: (031) 304 8082 email: admin@parachutesystems.co.za

Technical and Safety Information Notices issued by the Technical & Safety Committee of the International Parachuting Commission (FAI) are issued as information and help to parachuting nations and their affiliated members. The Information Notices are of an objective informative nature and there is no direct or implied criticism of any manufacturer or product intended. The Information Notices do not claim to be complete.

The Information Notices may result from:-

- 1 An incident or experience in the field being reported.**
- 2 A directive or notice issued by an aviation or government authority concerning parachuting operations or parachuting equipment.**
- 3 The issue of a notice by a manufacturer or by a National Parachuting Organisation. In the case of equipment being the subject of the bulletin the reader is advised to check with the manufacturer regarding the current status or position of that equipment.**

Technical & Safety Committee of IPC, IPC and FAI accept no liability for the use or misuse of any information contained in this Information Notice. The reader assumes all liability.

The Technical & Safety Committee, International Parachuting Commission, can be contacted on e-mail - lmcnulty@skydiveireland.ie

**Liam McNulty, Technical & Safety Committee, International Parachuting Commission.
03 March 2015**